

<b>Item #</b>	<b>Building</b>	<b>Floor Tiles (&amp; mastic)</b>	<b>Above Ceiling Fire Proofing</b>	<b>Mudded Pipe Fittings</b>	<b>Ceiling Tiles</b>	<b>Pipe Insulation</b>
6	<b>24. Dickinson - Constructed 1965</b>			<b>Revovated 2012-13</b>		
7	<b>Basement</b>	No	Abated	Abated	N/A	Abated
8	<b>First Floor</b>	No	No	Abated	No	Abated
9	<b>Penthouse</b>	No	No	Abated	N/A	Abated

<b>Mechanical Rooms</b>	<b>Gasket Material</b>	<b>Window Caulking</b>	<b>Transite</b>	<b>Dry Wall Compound</b>	<b>Crawl Space</b>	<b>Fire Doors</b>
Abated	Abated	N/A	Abated	Abated	N/A	Abated
N/A	Abated	Abated	Abated	Abated	N/A	No
N/A	Abated	N/A	Abated	N/A	N/A	No