

| Item # | Building | Floor Tiles (& mastic) | Above Ceiling Fire Proofing | Mudded Pipe Fittings | Ceiling Tiles | Pipe Insulation |
|--------|-------------------------------|---------------------------|--------------------------------------|----------------------------|------------------|--------------------|
| 2 | 42. Cayuga - Constructed 1972 | | | | | |
| 3 | First Floor | Yes | No | PACM | No | PACM |
| 4 | Second Floor | Yes | No | PACM | No | PACM |
| 5 | Third Floor | Abated | No | PACM | Abated | PACM |
| 6 | Fourth Floor | Abated | No | PACM | Abated | PACM |
| 7 | Fifth Floor | Abated | No | PACM | Abated | PACM |

| Mechanical Rooms | Gasket Material | Window Caulking | Transite | Dry Wall Compound | Crawl Space | Fire Doors |
|-------------------------|------------------------|------------------------|-----------------|--------------------------|--------------------|-------------------|
| | | | | | | |
| Abated | PACM | N/A | N/A | PACM | N/A | Yes |
| N/A | PACM | N/A | N/A | PACM | N/A | Yes |
| N/A | PACM | N/A | N/A | PACM | N/A | Yes |
| N/A | PACM | N/A | N/A | PACM | N/A | Yes |
| N/A | PACM | N/A | N/A | PACM | N/A | Yes |