

Item #	Building	Floor Tiles (& mastic)	Above Ceiling Fire Proofing	Mudded Pipe Fittings	Ceiling Tiles	Pipe Insulation
1	157. Harpur's Ferry Garage					

NYS Code Rule 56 does not require a building survey for buildings after January 1, 1974. However, we perform asbestos :

Mechanical Rooms	Gasket Material	Window Caulking Glazing	Transite	Dry Wall Compound	Crawl Space	Fire Doors

or structures for which original construction commenced on or surveys on any proposed demolition or renovation.